Chief Executive's Office

Accessibility Issues

Should you have any enquiries on the accessibility of premises, facilities and services of the Chief Executive's Office, please contact our Access Co-ordinator and Access Officer as follows –

Access Co-ordinator

Access Officer

Post : Deputy Private Secretary to Post : Executive Officer

Chief Executive (Administration)1

List of Barrier-free facilities in the CE's Office

	Barrier-free facilities	Features
1.	Accessible Entrance / Exit	Accessible ramp
	(Main entrance & staff entrance)	Tactile guide paths
		Double-wing lane gate
2.	Accessible lifts	Tactile guide path at lift zone
		Accessible lift with braille and tactile control buttons
		Handrails in lift car
3.	Accessible toilets	Accessible toilets on each office floor with grab rails on
		walls and door and emergency call bell
4.	Accessible carpark	Parking space marked with international symbol of
		accessibility on floor
5.	Accessible reception counter	Tactile guide paths
		• 24/7 manned reception counter to provide necessary
		assistance
6.	Visual fire alarm system	• Flashing red light, labelled "Fire Alarm 火警" in both
		English and Chinese installed at prominent locations
7.	Accessible route	Space allowed for manoeuvring wheelchair in corridor,
		lobby, path and similar areas